



<b>Brand:</b>	Audi	<b>Mileage(km):</b>	191511
<b>Model:</b>	A4 Avant	<b>Number of doors:</b>	5
<b>Model type:</b>	2.0 TDI S Line Autom	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	NL079B	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	2757	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	WAUZZZF4XHA072757	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Front
<b>First int. reg.:</b>	17/01/2018	<b>Power(kw):</b>	110
<b>First NL reg.:</b>	17/01/2018	<b>Transmission</b>	Automatic
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears</b>	7
<b>Weight (kg)(kg):</b>	1600	<b>Displacement(cc):</b>	1968
<b>Empty weight(kg):</b>	1500	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	282	<b>Fuel type:</b>	Diesel
<b>Top speed (km/h):</b>	213	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	5.1	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	3.9	<b>Energy label:</b>	D
<b>Average consumption (l/100 km):</b>	4.3	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	9	<b>CO2 (g/km):</b>	112
<b>Cargo space (l):</b>	1600	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	2145	<b>APK date:</b>	17/01/2021

## opties

## Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	245/35 R19	Vredestein	5
Tire left rear	Summer	Alloy	245/35 R19	Dunlop	4
Tire right front	Summer	Alloy	245/35 R19	Vredestein	5
Tire right rear	Summer	Alloy	245/35 R19	Dunlop	4

## Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
<b>Interior color:</b>	Black	<b>Maintenance booklet:</b>	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	25/02/2019	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	94828	<input checked="" type="checkbox"/> Vehicle special usage (None)

## Cleaning

- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

## Damages

 Not acceptable



Front bumper - Dent



Front left rim - Scratch



Voertuig rondom - Scratch



Rear left rim - Scratch



Rear right rim - Scratch



Front right rim - Scratch



Bonnet - Scratch

🔧 Damages

🔧 Acceptable

⚙️ Extra options







