



Brand:	BMW	Mileage(km):	154907
Model:	225	Number of doors:	5
Model type:	225xe iPerformance Centennial Executive	Vehicle length (cm):	
License plate:	KJ713H	Vehicle width (cm):	
Report code:	3932	Vehicle height (cm):	
Chassis number:	WBA2C71060V783932	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	26/09/2016	Power(kw):	100
First NL req.:	26/09/2016	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	6
Weight (kg)(kg):	1735	Displacement(cc):	1499
Empty weight(kg):	1635	Number of cylinders:	3
Wheelbase (cm)(cm):	267	Fuel type:	Hybride (Electro/Benzine) plug-in
Top speed (km/h):	202	Fuel tank capacity:	
Cons. in the city (l/100 km):		EU category:	Euro 6
Cons. outside the city (l/100 km):		Energy label:	A
Average consumption (l/100 km):		NL Tax Rate %:	
Acceleration (s):	6.7	CO2 (g/km):	46
Cargo space (l):	1735	Nb. of Axles:	2
Perm. max weight (kg):	2180	APK date:	26/09/2020

opties

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Winter	Alloy	205/55 R17	Continental	4
Tire left rear	Winter	Alloy	205/55 R17	Continental	4
Tire right front	Winter	Alloy	205/55 R17	Continental	4
Tire right rear	Winter	Alloy	205/55 R17	Continental	4

Additional information


No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (digitaal))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	20/06/2019	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	115524	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning


- ☒ Clean inside (Interior is clean)
- ☐ Clean outside

Damages

⊗ Not acceptable



Front left rim - Scratch







Rear left rim - Scratch



🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE