



<b>Brand:</b>	Alfa Romeo	<b>Mileage(km):</b>	105699
<b>Model:</b>	Giulia	<b>Number of doors:</b>	4
<b>Model type:</b>	2.2 Super Aut.	<b>Vehicle length (cm):</b>	
<b>License plate:</b>	SX635F	<b>Vehicle width (cm):</b>	
<b>Report code:</b>	1167	<b>Vehicle height (cm):</b>	
<b>Chassis number:</b>	ZAREAECUXH7521167	<b>Vehicle body type:</b>	
<b>Type of vehicle:</b>	Luxury	<b>Traction:</b>	Rear
<b>First int. reg.:</b>	02/01/2017	<b>Power(kw):</b>	110
<b>First NL reg.:</b>	27/08/2018	<b>Transmission:</b>	Automatic
<b>Color:</b>	Grey <input checked="" type="checkbox"/> <b>Metallic</b>	<b>Number of gears:</b>	8
<b>Weight (kg)(ka):</b>	1520	<b>Displacement(cc):</b>	2143
<b>Empty weight(ka):</b>	1420	<b>Number of cylinders:</b>	4
<b>Wheelbase (cm)(cm):</b>	282	<b>Fuel type:</b>	Diesel
<b>Top speed (km/h):</b>	221	<b>Fuel tank capacity:</b>	
<b>Cons. in the city (l/100 km):</b>	5.3	<b>EU category:</b>	Euro 6
<b>Cons. outside the city (l/100 km):</b>	3.5	<b>Energy label:</b>	C
<b>Average consumption (l/100 km):</b>	4.2	<b>NL Tax Rate %:</b>	
<b>Acceleration (s):</b>	7.6	<b>CO2 (g/km):</b>	109
<b>Cargo space (l):</b>	1520	<b>Nb. of Axles:</b>	2
<b>Perm. max weight (kg):</b>	2020	<b>APK date:</b>	07/01/2022

### opties

- |  |  |   |
|--|--|---|
| <input checked="" type="checkbox"/> Remote central locking           | <input checked="" type="checkbox"/> LED rear lights                    | <input checked="" type="checkbox"/> Climate control (analog)            |
| <input checked="" type="checkbox"/> Central locking system           | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Large screen navigation             |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Rain sensor                        | <input checked="" type="checkbox"/> Keyless start/stop                  |
| <input checked="" type="checkbox"/> Multifunctional steering wheel   | <input checked="" type="checkbox"/> Rear parking sensors               | <input checked="" type="checkbox"/> Electrically operated rear windows  |
| <input checked="" type="checkbox"/> Licht Sensor                     | <input checked="" type="checkbox"/> Front parking sensors              | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> Audio                            | <input checked="" type="checkbox"/> USB connection                     | <input checked="" type="checkbox"/> Electrically adjustable mirrors     |
| <input checked="" type="checkbox"/> ABS                              | <input checked="" type="checkbox"/> DAB+                               | <input checked="" type="checkbox"/> Central armrest front               |
| <input checked="" type="checkbox"/> Fog lamps                        | <input checked="" type="checkbox"/> Bluetooth car kit                  | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Alloy wheels                     | <input checked="" type="checkbox"/> Cruise control                     | <input checked="" type="checkbox"/> Leather steering wheel              |
| <input checked="" type="checkbox"/> Airbag(s)                        | <input checked="" type="checkbox"/> Airconditioning                    | <input checked="" type="checkbox"/> Lane assistance                     |
| <input checked="" type="checkbox"/> Halogen headlights               | <input checked="" type="checkbox"/> Climate control                    |   |

### Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	225/50 R17	Continental	5
Tire left rear	Summer	Alloy	225/50 R17	Continental	6
Tire right front	Summer	Alloy	225/50 R17	Continental	5
Tire right rear	Summer	Alloy	225/50 R17	Continental	6

### Additional information

<b>No. of keys:</b>	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input type="checkbox"/> Airco works
<b>Interior color:</b>	Brown	<b>Maintenance booklet:</b>		<input checked="" type="checkbox"/> Odorless
<b>Upholstery:</b>	Half stof/leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
<b>No. of seats:</b>	5	<b>Stamp date:</b>	07/01/2020	<input checked="" type="checkbox"/> Display ok
<b>No. of headrests:</b>	5	<b>Last turn mileage(km):</b>	61113	<input checked="" type="checkbox"/> Vehicle special usage (None)

### Cleaning

- Clean inside (Interior is clean)
- Clean outside

### Damages

Not acceptable



Front bumper - Scratch



Left sill - Scratch



Left sill - Scratch

🔧 Damages

⊕ Acceptable

⚙️ Extra options



