



Brand:	Audi	Mileage(km):	308434
Model:	A4 Avant	Number of doors:	5
Model type:	2.0 TDI Business Edition	Vehicle length (cm):	
License plate:	94RXT3	Vehicle width (cm):	
Report code:	3836	Vehicle height (cm):	
Chassis number:	WAUZZZ8K3CA033836	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front
First int. reg.:	22/08/2011	Power(kw):	105
First NL reg.:	22/08/2011	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	
Weight (kg)(kg):	1630	Displacement(cc):	1968
Empty weight(kg):	1530	Number of cylinders:	4
Wheelbase (cm)(cm):	281	Fuel type:	Diesel
Top speed (km/h):	200	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.5	EU category:	Euro 5
Cons. outside the city (l/100 km):	5	Energy label:	C
Average consumption (l/100 km):	5.9	NL Tax Rate %:	
Acceleration (s):	9.7	CO2 (g/km):	155
Cargo space (l):	1630	Nb. of Axles:	2
Perm. max weight (kg):	2125	APK date:	22/08/2022

opties

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Airconditioning |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Inflatable set | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Fog lamps | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Extendable passenger seat |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> Radio/CD player | <input checked="" type="checkbox"/> Extendable driver's seat |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Radio/CD/MP3 player | <input checked="" type="checkbox"/> Adjustable lumbar support driver's seat |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Adjustable lumbar support passenger seat |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Halogen headlights | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Leather steering wheel |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	All weather	Alloy	225/55 R16	delinte	6
Tire left rear	All weather	Alloy	225/55 R16	Pirelli	6
Tire right front	All weather	Alloy	225/55 R16	delinte	6
Tire right rear	All weather	Alloy	225/55 R16	Pirelli	6

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:	(serviceboekje (papier))	<input checked="" type="checkbox"/> Odorless
Upholstery:	Stof			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:	04/07/2018	<input checked="" type="checkbox"/> Display ok
No. of headrests:	5	Last turn mileage(km):	243894	<input checked="" type="checkbox"/> Vehicle special usage (None)

Cleaning

- ☒ Clean inside (Interior is clean)
- ☒ Clean outside (Polishing)

🔧 Damages

⊕ Not acceptable



Front bumper - Break



Bonnet - Rust formation



Right headlight - Weatherworn



Front bumper - Scratch





Front left rim - Scratch

🔧 Damages

⊕ Acceptable

⚙️ Extra options







AUTOF▲CTOR
SOFTWARE FOR AUTOMOTIVE